

TOPSIDE STUD BOLT TENSIONERS (LOAD CELL)

8

3

SERIAL NUMBERS

FROM BC2856

PRODUCT NO. STS6-LC

SHT 1 OF 1 SHTS

1	
2	
3	3932
4	6374

5	
6	
7	

7	
8	
9	

11

12 13

14 15

16

17

18 19

20

ITEM NO.	PART NUMBER	DESCRIPTION	QTY.	SPARE PART	SERVICE PART
1	BTC268CX001	CYLINDER	1	X	
2	BTC268PX002	PISTON (STS)	1	X	
3	STN1P4-C	ADAPTER	2		
4	FAS005ME006	SOCKET CUP PT SCREW M5 x 6	3		
5	STMC4	NIPPLE	1		
6	STFC4	COUPLER	1		
7	BTC268SX002	OUTER SEAL	1	X	✓
8	BTC268SX003	INNER SEAL	1	X	✓

- ALL PARTS ARE AVAILABLE TO BE ORDERED AS INDIVIDUAL SPARE PARTS (UNLESS MARKED WITH X).

- ALL PARTS MARKED WITH ✓ ARE **ONLY** AVAILABLE AS SERVICEABLE PARTS FOUND IN: **STS6LCTP2-K** SEAL KIT.

5

IMPORTANT

WHEN ORDERING SPARES YOU MUST STATE THE FULL PART NUMBER AND THE PRODUCT SERIAL NUMBER - FROM THE LABEL TO PROTECT YOUR WARRANTY ALWAYS USE GENUINE HI-FORCE PARTS.



STS6 TOPSIDE STUD BOLT TENSIONERS (LOAD CELL).

SERIAL NUMBERS


AV9656 TO BC2855

SPARE PARTS LIST NO.

STS6-LC

SHT 1 OF 1 SHTS

REVISION



IMPORTANT

WHEN ORDERING SPARES YOU MUST STATE THE FULL PART NUMBER AND THE PRODUCT SERIAL NUMBER - FROM THE LABEL TO PROTECT YOUR WARRANTY ALWAYS USE GENUINE HI-FORCE PARTS.

SERIAL NUMBERS **UP TO AV9655** SPARE PARTS LIST NO.

STS6-LC

SHT 1 OF 1 SHTS

9

10

11

12

13

14


15

16

17

18 19

REVISION 1 3932



5

NOTE 1:

20 IF CYLINDER IS REPLACED THEN ITEM 7 MUST BE REPLACED WITH STNP4-C AND THEN BONDED WASHERS NO LONGER REQUIRED

NOTE 2: INCLUDES BONDED WASHER

IMPORTANT

WHEN ORDERING SPARES YOU MUST STATE THE FULL PART NUMBER AND THE PRODUCT SERIAL NUMBER - FROM THE LABEL TO PROTECT YOUR WARRANTY ALWAYS USE GENUINE HI-FORCE PARTS.

www.hi-force.com

EARLIER VERSION OF ITEM 7 HAS 2 BONDED WASHERS

NEW VERSION IS INTERCHANGEABLE.